



Billy Pugh Co., Inc.

**USCG APPROVED TYPE V
WORK VEST DONNING INSTRUCTIONS**

MODEL WVO-50 & WVO-100

1



SLIP INTO JACKET

2



CLOSE CHEST STRAP BUCKLE

3



SECURE WAIST BELT;
PULL UNTIL SNUG

4



ADJUST SHOULDER STRAPS